



922-097

(Communication Server 1000 Upgrades to Rls. 5.0 for Technicians)

Total Questions: 25

Last Updated: Jan 03, 2008

Document version: 8.27.11

Thanks for purchasing techXams' Study Guide,

techXams' 922-097 study guide is a comprehensive compilation of questions and answers that have been developed by our team of certified professionals. In order to prepare for the actual exam, all you need is to study the content of this guide. An average of approximately 10 to 20 hours should be spent to study this guide and you will surely pass your exam. It's our guarantee.

Disclaimer

Neither this guide nor any material in this guide is sponsored, endorsed or affiliated with any of the respective vendor. All trademarks are properties of their respective owners.

Guarantee

If you study this guide properly and still unable to pass the exam, please send us a scanned copy of your official score at: refund@techeXams.ws. We will happily reimburse the cost of this study guide or send you an exchange of study guide of your choice free of cost.

Feedback

If you find any possible improvement, then please do let us know. We are always interested in improving the quality of this product. Feedback can be send at: feedback@techeXams.ws

Copyright

techXams holds the copyright of this material. techXams grants you a limited license to view and study this material, either for personal or commercial use. Unauthorized reproduction or distribution of this material, or any portion thereof, may result in severe civil and criminal penalties, and will be prosecuted to the maximum extent possible under law.

Question: 1

A customer is upgrading an existing Communication Server (CS) 1000S at Rls. 4.5 to a CS 1000E Rls. 5.0 Standard Availability. A CP-PM Call Server card is being installed during the upgrade. The CP-PM Call Server card has been installed into Slot 1 and configured. What is the next sequential step in the upgrade process?

- A. Reboot the card to begin the software installation.
- B. Connect the administration console to Port 0 of the NTAK19EC SDI cable.
- C. Insert the RMD containing the Rls. 4.5 customer database into the faceplate of the CP-PM Call Server card.
- D. Insert the bootable RMD containing software installation files into the faceplate of the CP-PM Call Server card.

Answer: B

Question: 2

A customer is upgrading an existing Communication Server (CS) 1000S at Rls. 4.5 to a CS 1000E Rls. 5.0 with a single IP Media Gateway 1000E chassis. In this configuration, which slot in the IP Media Gateway houses the Media Gateway Controller Card?

- A. Slot 0
- B. Slot 1
- C. Slot 2
- D. Slot 3

Answer: A

Question: 3

A customer with a Communication Server (CS) 1000E at Rls. 4.5 with an Media Gateway (MG) 1000T containing three chassis is planning to migrate the functionality of the MG 1000T into the CS 1000E High Availability system, and then upgrade the system to Rls. 5.0. The system Signaling Servers are Nortel ISP 1100 servers. What must be done to the Signaling Server to complete the upgrade?

- A. Upgrade the server software to Rls. 5.0 only.
- B. Replace the hardware to CP-PM Signaling Server.
- C. No action is required; the Signaling Server can remain at Rls. 4.5.
- D. Upgrade the memory to 1 GB followed by a software upgrade to Rls. 5.0.

Answer: D

Question: 4

A customer is upgrading a Communication Server 1000E Rls. 4.5 to a CS 1000E Rls. 5.0 Standard Edition (SE) 1000E chassis. Which components are not required for the upgrade?

- A. SSC Card
- B. Call Server
- C. Voice Gateway
- D. Nortel IPS 1100

Answer: A

Question: 5

A customer is upgrading a Communication Server 1000E Rls. 4.5 to a CS 1000E Rls. 5.0. A CP-1000E chassis is being used. Which two statements correctly describe the upgrade process?

- A. Rls. 5.0 software is installed on the server.
- B. The Software Installation Manager (SIM) is used to install the Rls. 5.0 software on the server.
- C. Rls. 5.0 software is installed on the server. A bootable RMD is used to format the hard drive.
- D. A bootable RMD is used to format the hard drive. Rls. 5.0 software is installed on the server.

Answer: C, D

Question: 6

A customer is upgrading a Communication Server 1000E Rls. 4.5 to a CS 1000E Rls. 5.0. Standard Edition (SE) 1000E chassis. During the upgrade, the system administrator receives the following error message: "Error: Terminal format. W". Which action should the administrator take to resolve the error?

- A. Reformat the hard drive.
- B. Reinstall the Rls. 5.0 software.
- C. Reinstall the Rls. 4.5 software.
- D. Change the terminal format.

Answer: D

922-097 Demo Exam