



132-S-911

(Specialist IP Telephony Implement Support Elective Exam)

Total Questions: 199

Last Updated: Mar 28, 2009

Document version: 8.27.11

Thanks for purchasing techXams' Study Guide,

techXams' 132-S-911 study guide is a comprehensive compilation of questions and answers that have been developed by our team of certified professionals. In order to prepare for the actual exam, all you need is to study the content of this guide. An average of approximately 10 to 20 hours should be spent to study this guide and you will surely pass your exam. It's our guarantee.

Disclaimer

Neither this guide nor any material in this guide is sponsored, endorsed or affiliated with any of the respective vendor. All trademarks are properties of their respective owners.

Guarantee

If you study this guide properly and still unable to pass the exam, please send us a scanned copy of your official score at: refund@techeXams.ws. We will happily reimburse the cost of this study guide or send you an exchange of study guide of your choice free of cost.

Feedback

If you find any possible improvement, then please do let us know. We are always interested in improving the quality of this product. Feedback can be send at: feedback@techeXams.ws

Copyright

techXams holds the copyright of this material. techXams grants you a limited license to view and study this material, either for personal or commercial use. Unauthorized reproduction or distribution of this material, or any portion thereof, may result in severe civil and criminal penalties, and will be prosecuted to the maximum extent possible under law.

Question: 1

Your customer is unable to light message waiting lights at a small branch office using a shared Intuity voice mail system on a QSIG network running DCS. What is the first command you should execute?

- A. list ip-interfaces
- B. list media-gateway
- C. display-ip-network-region <x>
- D. status station <station number>

Answer: C

Question: 2

DHCP option codes 128 to 254 are reserved for site-specific options. A single number out of this range is commonly utilized by vendors to configure their Avaya IP phones via DHCP (Option 176). Which additional option code supports vendor-specific options?

- A. 3
- B. 23
- C. 43
- D. 63

Answer: B

Question: 3

What color is the LED when a TN circuit pack is executing a test?

- A. Red
- B. Green
- C. Yellow
- D. Amber

Answer: B

Question: 4

You are migrating from a Definity server to an S8500/S87XX server. Where is the IPSI board located?

- A. It is always placed into slot number 1.
- B. The location depends on which media server is used.
- C. It can be slotted into any available media gateway slot.
- D. The location depends on which media gateway is used.

2

Answer: C

Question: 5

Which Communication Manager feature is used to reduce bandwidth limit has when IP WAN

- A. Inter-Gateway
- B. Intra-Gigabit
- C. Intelligent
- D. Intelligent Gate

Answer: Pending

Question: 6

Which two Avaya Call Manager statistics of a specific extension are

- A. Status station
- B. Display station
- C. List trace station
- D. Display trace station

Answer: B

Question: 7

Which two statements are true

- A. A DHCP server is
- B. A DHCP server c
- C. One DHCP serve

re the service

Answer: A, C

Question: 8

A customer has purchased 20 Avaya IP telephones for a period of three years. Knowing that the IEEE 802.3af standard has been implemented, the customer decided to purchase a C360-PWR switch to provide in-line power to the IP telephones. However, only 15 of the phones power up when they are connected to the C360-PWR. Upon investigation you discover the five phones which would not receive power from C360-PWR are Generation 1 models that are not 802.3af

compliant. Which three methods should you use to power these phones? (Choose three.)

- A. 356A adapter
- B. Individual power
- C. 1152A1 mid-sp
- D. Other vendor 80
- E. IP phone 4600 E

Answer: A, B, D

Question: 9

In an Enterprise Surviv server?

- A. Save trans
- B. Save trans all
- C. Save ESS setting
- D. Save trans clust

relations to your ESS

Answer: A

Question: 10

An Avaya IP phone is CLAN and TN2302 IP properly on the CLAN audio quality is poor disconnects. Which t

- A. Insufficient IP m
- B. Use of the G.711
- C. Implementing M

re the TN799 s registered All is answered. The of the users choose two.)

Answer: A, B

132-S-911 Demo Exam